

Inspection Report

John Smyth

Property Address: 1234 Main Street Santee CA 92071



The Property Inspection Pros

Jeff Duncan WWW.TPIPS.COM jduncan@tpips.com Cell: 760-525-5340 Certified Professional Inspector



Table of Contents

Cover Page1
Table of Contents
Intro Page 4
<u>1 Roofing8</u>
2 Exterior
3 Electrical System 13
<u>4 Garage19</u>
5 Water Heater 23
<u>6 Interiors27</u>
7 Plumbing System
8(A) Hall Bathroom Downstairs43
8(B) Hall Bathroom Upstairs 44
8(C) Master Bathroom
<u>9 Laundry</u>
10 Fireplaces/ Chimneys 50
11 Detectors, Safety, Security 52
12 Heating Equipment 54
13 Cooling Equipment57
14 Ventilation and Insulation60
15 Structural Components 62
16 Built-In Kitchen Appliances
17 Gas, Electric, Water Shut-Off Locations 69
General Summary71

Date: 11/2/2024	Time: 02:00 PM	Report ID:
Property:	Customer:	Real Estate Professional:
1234 Main Street	John Smyth	
Santee CA 92071		
IN ATTENDANCE DURNING THE	TYPE OF BUILDING:	APPROXIMATE YEAR BUILT (BASED
INSPECTION:	CONDOMINUIM	ON BUYERS AGENT-BUYER-OR/
BUYER, BUYER'S AGENT, INSPECTOR		MLS):
		1997, OLDER
WEATHER TYPE:	TEMPERATURE:	GROUND/ SOIL SURFACE
PARTLY CLOUDY	67, DEGREES	CONDITIONS:
		DRY
RAINED IN THE LAST 3 DAYS:	NUMBER OF LEVELS:	UTILITIES:
NO	2	ALL UTILITIES WERE ON
OCCUPIED:		
YES		

PLEASE READ THE FOLLOWING INFORMATION

The purpose of this inspection is to assess the general condition of the property. Our Inspectors are Generalists and not Specialists. Further evaluated by licensed contractors who through their evaluations may identify additional material defects or adverse conditions that could result in injury or lead to costs that would significantly affect your evaluation of the property. We highly recommend that you follow our further evaluation recommendations as outlined in your inspection report prior to the end of your contingency period. Special attention is given to identifying deficiencies in systems and components that require immediate repair, or that need further investigation. Chips, cracks, blemishes, etc. that are cosmetic in nature are not reportable items. The Client(s) is/are therefore advised to inspect and evaluate such items personally and take corrective action(s) if concerned.

This report is the exclusive property of The Property Inspection Pros and the client(s) whose name appears herewith, and its use by any unauthorized persons is strictly prohibited. The observations and opinions expressed within this report are those of The Property Inspection Pros and supersede any alleged verbal comments. We inspect all of the systems, components, and conditions described in accordance with the International Association of Certified Home Inspectors Standards of Practice of a General Home Inspection.

SCOPE OF THE INSPECTION:

The Property Inspection Pros Inspectors will inspect all properties in accordance with the International Association of Certified Home Inspectors, Standards of Practice of a General Home Inspection. We respectfully ask that you read and become familiar with these Standards of Practice at the following link: **STANDARDS OF PRACTICE** If you have any questions or concerns of these Standard of Practice of a General Home Inspection please contact us 760-525-6154.

The Property Inspection Pros provides you with a basic overview of the condition of the property at the time

and date of the inspection. The purpose of your Home Inspection is to evaluate the general condition of the structure at the noted address. This includes determining whether systems are still performing their intended functions. The inspection to be performed for Client(s) is a limited, visual, non-invasive, non-destructive, nontechnically exhaustive evaluation, performed for a determined fee, designed to identify material defects in the systems, structures, and components of the above-referenced primary building and its associated primary parking structure as they exist at the time and date of the inspection. A material defect is a condition that significantly affects the value, desirability, habitability or safety of the building. Style or aesthetics shall not be considered in determining whether a specific system, structure, or component is defective. The inspection shall be limited to those specific systems, structures, and components that are present and visually accessible at the date and time of the inspection. Components and systems shall be operated with normal user controls only and as conditions and limitations permit. The inspection provides a general overview of the more obvious repairs or replacement that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not. There are limitations to the scope of this Inspection.

The inspection report shall describe and identify the inspected systems, structures, and components of the building and identify material defects in those systems, structures, and components observable during the inspection, with limitations. Defects that are concealed/ are not accessible are specifically disclaimed. This includes defects that are concealed in/ behind the walls and wall coverings, in/ behind the floors and floor coverings, concealed by fresh paint, soil, vegetation, or other landscaping, or by stored items throughout the interior or exterior of the house/ property. Client(s) understands that the inspector shall use specialized tools at aid in the inspection process with the Client(s) best interest in mind, but that some concealed defects may go undetected and are unable to be reported on. Inspectors will not find conditions that may only be visible when storage or furniture is moved. Inspectors do not remove wallpaper, look behind pictures, and move furniture / stored items, lift flooring (including carpet) to look underneath, or cut / remove vegetation / landscaping. Client(s) agrees to hold the Inspector and The Property Inspection Pros harmless if Client(s) or any of the Client(s) representatives discovers concealed defects that were undetected at the time and date of the inspection.

LIMITATIONS, EXCEPTIONS AND EXCLUSIONS:

Excluded from this limited, visual, non-intrusive, non-destructive, non-technically exhaustive generalist inspection of the structure is any system, structure, or component of the building which is inaccessible, concealed from view, or cannot be inspected due to circumstances beyond the control of Inspector, or which Client(s) has agreed is not to be inspected. In addition to concealed defects, the following are excluded from the scope of this inspection unless specifically agreed to in writing:

1. Determining compliance with each manufacturers' specifications, researching building codes for the year built or modified, ordinances, regulations, covenants, or other restrictions (such as HOA rules), including local interpretations thereof. 2. Obtaining or reviewing information from any third-parties including, but not limited to: government agencies (such as permits), component or system manufacturers (including product defects, recalls or similar notices, unless agreed to in writing), square footage, contractors, managers, sellers, occupants, neighbors, consultants, homeowner or similar associations, attorneys, agents or brokers. The Property Inspection Pros does not endorse nor inspect unpermitted structures or additions and exclusively disclaims them from our inspection and inspection report. Geotechnical, engineering, structural, architectural, geological, hydrological, land surveying or soils-related examinations. 3. Examination of conditions related to animals, rodents, insects, wood-destroying insects, organisms, mold, and mildew or the damage caused thereby. Mold determination is not part of this inspection (unless agreed to in writing). If evidence of unidentified stains is noted, a specialist should be consulted to determine type. Mold has been known to cause health risks. The Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property. 4. Certain factors relating to any systems, structures, or components of the building, including, but not limited to: Recalls, adequacy, efficiency, durability or remaining useful life, costs to repair, replace or operate, fair market value, marketability, quality, or advisability of purchase. 5. Environmental hazards or conditions, including, but not limited to, toxic, reactive, combustible, corrosive contaminants, wildfire, geologic or flood. 6. Dismantling of any system, structure, or component, or perform any intrusive or destructive examination, test or analysis. Inspector is limited to evaluating components from standard service or access covers. 7. Examining or evaluating fire-resistive gualities of any system, structure or component of the building. 8. Systems, structures, or components of the building, which are not permanently installed (such

as refrigerators, washing machines and dryers, window AC, etc). 9. Systems, structures, or components that are not part of the main house, unless specifically identified in the written inspection report, 10, Common areas, or systems, structures, or components thereof, including, but not limited to, those of a common interest (HOA). 11. Examining or evaluating the acoustical or other nuisance characteristics of any system, structure, or component of a building, complex, adjoining properties, or neighborhood. 12. Operating or evaluating low voltage electrical, antennas, security systems, cable or satellite television, telephone, remote controls, radio controls, timers, intercoms, computers, computer networks, photo-electric, motion sensing, or other such similar non-primary electrical power devices, exterior yard lighting, components, or systems. 13. Evaluation of any pool/spa, barn, fence, irrigation system, built in BBOs or other structures unless agreed to in writing. 14. Evaluation of any type of electric Solar system and related components on or off the house/ structure. 15. Examining or operating any sewage disposal system or component including, but not limited to: septic tanks and/or any underground system or portion thereof, or ejector pumps for rain or waste. 16. Environmental evaluation and inspection. The building inspection is not intended to determine the presence of lead, radon, mold, Polychlorinated biphenyls (PCB's), mildew, urea- formaldehyde, asbestos, sulfur, contaminated drywall, Chinese drywall, or other toxins in the building, ground, water or air. 17. It is beyond the scope of this inspection to determine if any system or component is, has been, or will be part of any product, component or system recall. We highly recommend Client(s) subscribe or contact the CPSC (Consumer Product Safety Commission) for recall information regarding any system or component if concerned.

A home inspection is not a pest inspection. Any observations which the inspector may make in this report regarding evidence of peats or wood destroying organisms, are not a substitute for an inspection by a qualified licensed pest control operator or exterminator. Your inspector may only report on a portion of the currently visible conditions and cannot render an opinion regarding their cause, condition, or remediation. We recommend a careful review of any recent pest control inspection report concerning pest activity or wood destroying organisms on this property. If no such report is available, we recommend that a pest control inspection be performed on the property prior to the end of your contingency period.

Thank you for choosing The Property Inspection Pros for your property inspection needs. We hope the information contained in your report is beneficial to you. If there are areas that you have questions about or would like further explanation, please don't hesitate to call us. Your satisfaction is important to us.

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

Inspected (IN) = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI) = I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

<u>Repair or Replace (RR)</u> = The item, component or unit is not functioning as intended, or needs further

inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Information Only (IO) = This item, is for your information only.

Please accept this one year FREE membership to HOCOA your home repair network on my behalf. It's easy to get started just go to this link <u>HOCOA</u> and fill out the short form. You will then receive your FREE membership kit in the mail in a few days.

THE TERMS 'FRONT,' 'REAR,' 'LEFT,' AND 'RIGHT' ARE USED IN REFRENCE TO THE PROPERTY AS VIEWED FROM THE FRONT ENTRY DOOR.

Inspected in accordance with "THE INTERNATIONAL ASSOCIATION OF CERTIFIED HOME INSPECTORS STANDARDS OF PRATICE AND CODE OF ETHICS".

This home is older and the home inspector considers this while inspecting. It is common to have areas that no longer comply with current code. This is not a new home and this home cannot be expected to meet current code standards. While this inspection makes every effort to point out safety issues, it does not inspect for code. It is common that homes of any age will have had repairs performed and some repairs may not be in a workmanlike manner. Some areas may appear less than standard. This inspection looks for items that are not functioning as intended. It does not grade the repair. It is common to see old plumbing or mixed materials. Sometimes water signs in crawlspaces or basements could be years old from a problem that no longer exists. Or, it may still need further attention and repair. Determining this can be difficult on an older home. Sometimes in older homes there are signs of damage to wood from wood eating insects. Having this is typical and fairly common. If the home inspection reveals signs of damage. The home inspection does not look for possible manufacturer re-calls on components that could be in this home. Always consider hiring the appropriate expert for any repairs or further inspection.

1. Roofing

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors. We do not verify that the materials are installed according to manufacturer's specifications. We recommend that all stains be further evaluated by a gualified licensed roof contractor



Note: We recommend that all roofs be inspected and maintained periodically by a qualified licensed roof contractor.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

prior to the end of your contingency period and repaired as necessary.

IN NI NP RR IO Items



1.0 ROOFING - CONDO

Comments:

This inspection is being performed on a condominium. A condo inspection is limited to the interior space only, and does not include the roof in any way. Please contact the HOA for information regarding the condition of the roof, repair history, or any other roof concerns.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. However, we do not predict the remaining life, the integrity, or guarantee that the roof will not leak. We also recommend obtaining a home warranty that includes coverage for the roof (s). Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Note: This roof inspection reports on the type and condition of the roofing materials, missing and/or damaged materials, and attachments (excluding solar systems, antennas, etc.) where visible. This does not constitute a warranty, guarantee, roof certification, or life expectancy evaluation of any kind. Roofs are not water tested for leaks. The condition of the roofing underlayment material was not verified/inspected. For further evaluation and a roof certification, we recommend you consult a qualified licensed roofing contractor prior to the end of your contingency period.

2. Exterior

The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.

Property Notes: Identifying the location of property lines, easements, and other property restrictions, and their implications to existing structures are beyond the scope of our general home inspection.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items

2.0 EXTERIOR CONDO Comments:

The exterior was not evaluated as part of this condo inspection. A condo inspection is limited to the interior only and not an evaluation of the exterior. Common areas are not part of a condo inspection. If concerned we recommend contacting the HOA prior to the end of your contingency period.



2.1 EXTERIOR (GENERAL COMMENTS)

Comments:

Unsecured items in a yard may be hazardous. Inspecting unsecured items for proper installation is beyond the scope of our general home inspection. We recommend that any unsecured items be checked by you or by a qualified person to ensure proper installation.



2.2 GRADING AND DRAINAGE (WITH RESPECT TO ITS EFFECT ON THE BUILDING)

LOT DRAINAGE: BURRIED DRAIN LINES

Comments:

IN NI NP RR IO Items




IN NI NP RR IO Items

(1) Ground drain lines were visible in the yard at several areas. These drains are not tested for functional flow or adequacy. It is important to maintain these drains and prevent debris from entering. We recommend having all ground drain lines inspected and cleaned after moving into the property and on a periodic basis by a qualified person.

(2) The rear platform has been built at the same level as the interior slab/ floor. The ideal building will have interior floors that will be several inches higher than the exterior grade. This property does not meet this ideal requirement. Repairs may be need to prevent damage/moisture intrusion. We recommend further evaluation and necessary repairs by a licensed landscaping contractor.



2.2 Item 1(Picture)




2.3 WALL CLADDING FLASHING AND TRIM

SIDING MATERIAL: STUCCO, WOOD TRIM

Comments:

(1) There is damaged/ deteriorated stucco observed at several areas. We recommend necessary repairs where needed by a licensed stucco contractor.

(2) Routine Maintenance Tip: Seal all gaps, cracks and openings in the stucco. This includes cracks around windows and doors, gaps between flashing and stucco and small holes in the siding. This is a normal maintenance items and should be done on an annual basis. Small cracks and gaps can cause big problems over time due to water infiltration and pest infestation.



2.4 DOORS (EXTERIOR)

Comments:

A pet door is present at the exterior garage door. These modifications can cause damage to the door by letting in rain. These modifications can also reduce the security of the door by making it easier for someone to enter or reach inside and unlock the

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items

door. We recommend sealing the door or replacing the door by a qualified person



2.4 Item 1(Picture)



2.5 WINDOWS (INTERIOR AND EXTERIOR)

WINDOWS: RETROFIT, DOUBLE PANE VINYL, DOUBLE PANE ALUMINUM

Comments:

(1) There is a window in the master bathroom that is very difficult to open. It will not open or close fully. We recommend necessary repairs by a qualified licensed window contractor.



2.5 Item 1(Picture)

(2) The windows throughout the house were dirty at the time of the inspection. This condition limits the inspectors ability to observed fogged windows (failed seals in double pane windows) or cracked windows. We recommend that all the windows be professionally cleaned and then inspected by this company or by a qualified licensed window contractor prior to the end of your contingency period.

(3) Dual Pane Window Note - Failed seals in insulated glass dual pane windows are not always visible or detectable. In some instances the home inspector may not be able to disclose the exact condition of every window, depending on the ambient conditions or if the windows are dirty at the time of the inspection. Windows are reported as they are observed at the time of the inspection only. If you have present or future concerns regarding the integrity of the dual pane thermal seals, we strongly recommend that you

IN NI NP RR IO Items

IN NI NP RR IO Items


consult with a qualified licensed window contractor for further evaluation. This inspection is not a guarantee of any kind regarding the integrity of the dual pane windows.

(4) Retrofit windows are inspected for proper operation and visible evidence of defects such as damage which may result from leaks. A home inspection is a generalist and not a specialist. A general inspection cannot guarantee against leaks specifically due to lack of rail. To do so would require water testing with specialized equipment by a specialist/ contractor in this field. Replacement windows are not flashed the same way as original windows and we cannot determine the adequacy of the flashing. It is important for you or a qualified professional to inspect these windows after the next rain for any signs of leaking. Failure to do so can result in property damage including damage to the framing members, flooring and drywall.

(5) Condensation was observed between the panes of glass at a window in the dinning area. This occurs when the seal has failed between the panes of glass, and ambient air has entered the assembly. Replacement of the glass is required. Since some failed windows may not be easily found due to changing ambient conditions (heat, humidity, etc). We recommend having all of the windows reviewed by a licensed window contractor to determine how many windows require repair/replacement. We recommend repairing or replacing all windows that have failed window seals by a licensed window contractor.



2.5 Item 2(Picture)



2.6 SAFETY GLASS (EXTERIOR)

2.7 DRIVEWAYS, PATIOS, WALKWAYS (HARDSCAPE) Comments:

There is missing, cracked and damaged mortar between several stones at the rear patio area. We recommend necessary repairs by a licensed concrete contractor.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

3. Electrical System

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report any observed aluminum branch circuit wiring. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary

distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only


IN NI NP RR IO Items



3.0 MAIN PANEL

distribution system; or Built-in vacuum equipment.

MAIN PANEL CAPACITY: APPEARS TO BE ADEQUATE ELECTRIC SERVICE CONDUCTORS: BELOW GROUND, 220 VOLTS



3.1 SUB PANEL

Comments: Photo of the sub electrical panel.



3.1 Item 1(Picture)



3.2 CIRCUIT BREAKERS/ FUSES

PANEL TYPE: CIRCUIT BREAKERS

Comments:

Photo inside of the sub electrical panel.


The dead front cover was removed at the time of the inspection and the breakers, wiring

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items

and grounding were inspected. Appears to be functioning as intended.



3.2 Item 1(Picture)



3.2 Item 2(Picture)



3.3 BRANCH CIRCUIT CONDUCTORS/ WIRING BRANCH WIRE 15 AND 20 AMP: COPPER

WIRING METHODS: ROMEX, CONDUIT Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

(1) Wires for some lighting fixtures in the attic space were observed to be unsecured. We recommend necessary corrections by a qualified licensed electrician.



3.3 Item 1(Picture)

(2) Unprotected Romex was present in the attic adjacent to the attic scuttle. Romex located within 6 feet of the attic scuttle must be protected from damage. We recommend adding protection to the Romex in attic by the access a qualified licensed electrician.



3.3 Item 2(Picture)


(3) Home inspectors do not evaluate individual circuits for capacities, or identify which receptacles are on a particular circuit, or verify the labeling of the breakers. If concerned about the capacity of individual circuits for their capacities and the correct labeling of the breakers we recommend further evaluation by a qualified licensed electrician prior to the end of your contingency period for verification of these items.



IN NI NP RR IO Items

IN NI NP RR IO Items

The stairwell three-way light does not light the bottom of the stairs fully. This is a safety concern and corrections are needed. We recommend necessary repairs by a qualified licensed electrician.



3.7 POLARITY AND GROUNDING (OF A REPRESENTATIVE NUMBER OF RECEPTACLES)

Comments:

Photo of a receptacle being tested.

A representative number of receptacles throughout the property were tested for power, polarity and grounding according to our standards-of-practice. These receptacles observed to be ok at the time of the inspection unless otherwise noted.




3.7 Item 1(Picture)

3.8 RECEPTACLE(S) ISSUES
3.9 220 OUTLET(S)
3.10 OPERATION OF GFCI (GROUND FAULT CIRCUIT INTERRUPTERS) Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

All accessible GFCI receptacles were tested and were functioning properly at the time of the inspection unless otherwise reported. Sometimes a tripped GFCI receptacle may be difficult to find. If you do not have power at certain receptacles please check all GFCI's and reset the tripped GFCI receptacle. If the GFCI doesn't reset than replacement of the GFCI receptacle will be required.



3.10 Item 1(Picture)



3.12 JUNCTION BOXES (OBSERVABLE)

3.13 EXTERIOR LIGHTING

EXTERIOR LIGHTING CONTROL: STANDARD SWITCHED

Comments:

(1) The exterior light fixtures were not sealed where the fixture meets the wall. This condition could allow moisture intrusion in this area. We recommend sealing exterior light fixtures where they meet the wall by a qualified person.



3.13 Item 1(Picture)

(2) A representative number of exterior lights were tested and were found to be functional at the time of the inspection.

IN NI NP RR IO Items

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report. All electrical concerns/ defects should be considered a safety concern and should be corrected.

4. Garage


The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Garage door operators; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when more than representative reverses a representative reverses of the reverse of



automatically reverse or stop when meeting reasonable resistance during closing; Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Garage door operator remote control transmitters, Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments. The home inspector is not required to: Move personal items, panels, furniture, equipment that obstructs access or visibility.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



4.0 GARAGE VEHICLE DOOR(S)

GARAGE VEHICLE DOOR MATERIAL: METAL - PANEL


Comments:

Garage door photo(s).

The garage vehicle door hardware including the door, track, and springs appear to be functioning as intended.



4.0 Item 1(Picture)



4.1 GARAGE VEHICLE DOOR OPENER(S)

Comments:

(1) Sensors are in place, were tested and will reverse the garage door.

(2) As of July 1, 2019 all garage door openers are required to have a battery back up that is designed to operate when activated due to an electrical outage. Replacement of the garage doors connected to an automatic opener requires updating to a battery backup type. Verification of compliance is beyond the scope of this inspection. Client is advised to verify compliance and update if needed.

(3) There were no hand held garage door remote controls present at the time of the inspection. The garage door was operated by the garage door opener wall control. We recommend asking the seller to leave behind the hand held garage door remote controls.

(4) Due to the high number of garage door openers that fail to auto-reverse when

IN NI NP RR IO Items

IN NI NP RR IO Items

testing the garage door openers pressure-activated auto-reverse feature which could cause severe damage to the garage door and its related components when it fails to auto-reverse, we did not test the garage door openers pressure-activated auto-reverse feature at the time of the inspection. We recommend having the garage door(s) pressure-activated auto-reverse feature tested prior to the end of your contingency period by a qualified licensed garage door contractor.

(5) The emergency release cord is missing. The emergency release cord is a safety item that is required to be mounted with the handle no more than 6 feet from the floor. We recommend correction by a qualified person.



4.1 Item 1(Picture)



4.2 GARAGE CEILING

Comments:

(1) Paint is flaking/ failing at several areas and needs prep and paint. We recommend prep and paint where needed by a licensed paint contractor.




4.2 Item 1(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items

(2) The ceiling has typical cosmetic wear. You may wish to view this for yourself and have necessary repairs made by a qualified person.

(3) There are several holes/ damage observed at the garage ceiling. We recommend necessary repairs where needed by a qualified licensed contractor.



4.2 Item 2(Picture)

4.3 GARAGE WALLS (INCLUDING FIREWALL SEPERATION)

Comments:

(1) Due to occupants personal items, not all areas of the property were visible and accessible at the time of the inspection. Several windows, doors, outlets, walls, flooring, and other areas were obstructed from view and could not be inspected. The home inspector does not move personal items, panels, furniture, equipment, plant life, soil, debris, ect. that obstructs their access or visibility. We recommend that you conduct a careful evaluation during your final walk-through or prior to the end of your contingency period to ensure that there are no hidden defects. All doors, windows, and outlets should be tested and verified for proper operation prior to the end of your contingency period by a qualified person. If any damage is observed we recommend asking the seller about it. We recommend that any damage found be repaired or replaced by a qualified licensed contractor in the appropriate trade.

(2) The walls have typical cosmetic wear. You may wish to view this for yourself and have necessary repairs made as needed by a qualified person.

4.4 GARAGE FLOOR/ SLAB

Comments:

Due to stored personal items not all areas throughout the property were visible and accessible at the time of the inspection. The slab and other areas were obstructed from view and could not be inspected. The home inspector does not move personal items, panels, furniture, equipment, plant life, soil, debris, ect. that obstructs their access or visibility. We recommend that you conduct a careful evaluation during your final walk-through or prior to the end of your contingency period to ensure that there are no hidden defects. All doors, windows, and outlets should be tested and verified for proper operation prior to the end of your contingency period by a qualified person. If any damage is observed we recommend asking the seller about it. We recommend that any damage found be repaired or replaced by a qualified licensed contractor in the appropriate trade.



4.5 FIRE-RATED DOOR

IN NI NP RR IO Items

Comments:

The door between the house and garage did not have a Fire Rating Certificate or Plate. Without a plate, I could not confirm whether the door meets fire code safety requirements. We recommend further evaluation by a licensed door contractor. The "fire door" is required to meet one of the following characteristics:1-3/8 inch thick solid wood, 1-3/8 inch thick steel shell door with Honeycomb core, Fire-rated (with certificate plate). If the door is not rated as a fire door we recommend replacing by a qualified licensed door contractor for safety.



4.6 FIRE-DOOR CLOSING DEVICE

Comments:

(1) The door to the garage has a door stopper installed at the bottom of the door. The door stopper defeats the auto closer, which is required. We recommend removal of the door stopper to maintain the integrity of the fire wall and fire door.



4.6 Item 1(Picture)

(2) A self-closing device was present at the fire door and was operating properly when tested. The door closes and latches within 3 seconds without assistance as required.



IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only


The garage was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

5. Water Heater

The home inspector shall observe: The water heating equipment, including the energy source, venting connections, temperature/pressure-relief (TPR) valves, Watts 210 valves, and seismic bracing, the capacity of the water heating equipment if labeled. The Temperature Pressure Relief (TPR) valve is not tested because the TPR valve is prone to leaking once activated. The inspector is not required to: measure the capacity, temperature, age, life expectancy or adequacy of the water heater, evaluate wait time to obtain hot water at fixtures, or perform testing of any kind to water heater elements.

IN=Inspected, NI=Not Inspected, NP=Not Present, RR=Repair or Replace, IO=Information Only

IN NI NP RR IO Items



5.0 Item 1(Picture)

IN NI NP RR IO Items


IN NI NP RR IO Items



5.0 Item 2(Picture)

(2) The temperature of the water was tested using a thermal camera during the inspection and was found to be operating within normal range.

(3) The gas supply pipe at the water heater did not contained a drip leg/ sediment trap. This may have been standard at the time of installation but now is highly recommended. The purpose of a drip leg is to prevent sediment/ debris from entering and clogging the water heater gas valve which could cause the water heater to shut down. We recommend having a drip leg installed by a qualified licensed plumber.



5.0 Item 3(Picture)


(4) The water heater does not have a "Thermal Expansion Tank" installed to prevent a possible leak at the T&P or "pop-off" valve. Recent changes in code require one when a new water heater is installed. This change is not retroactive on older previously installed Gas/LP water heaters. There were no leaks or drips at the T&P valve during inspection. If your water heater does begin to drip or leak, then a thermal expansion tank may be needed. We recommend installing a thermal tank by a qualified licensed plumber as an

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items


upgrade.



5.0 Item 4(Picture)

(5) A leak pan is not installed under the water heater. We recommend installing a leak pan under the water heater by a qualified licensed plumber.

(6) The water heater is an older unit/ 10 plus years, and repairs or even failure can be expected. Based on manufacture's statistics the average life of a water heater is 7-10 years. We recommend replacing the water heater by a qualified licensed plumber.
(7) The water heater gas pipe fittings appear to have white teflon tape installed on them. This is non standard. White teflon tape is intended for use on water pipe fittings. We recommend necessary corrections by a qualified licensed plumber.



5.0 Item 5(Picture)



5.1 MAIN WATER HEATER (PLATFORM & STRAPPING)

Comments:

The water heater is adequately strapped as required.



5.3 MAIN WATER HEATER (TEMPERATURE & PRESSURE RELIEF VALVE)

IN NI NP RR IO Items

The water heater in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

6. Interiors

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments. The home inspector is not required to: Move personal items, panels, furniture, equipment, or anything that obstructs access or visibility.



Inspection of the home interior does not include testing for mold, radon, asbestos, lead paint, or other environmental hazards. If concerned we recommend further evaluation by a qualified licensed professional in the appropriate trade prior to the end of your contingency period.

Note: All moisture stains should be investigated until the client is satisfied that the condition is sufficiently understood. Where there are concerns regarding water leaks or infiltration, we recommend that a qualified industrial hygienist evaluate for mold, fungus, or other microbial material prior to the end of your contingency period.

Determining if damage, the presence of organic growths, moisture or wood rot behind walls, base boards, floors and ceiling coverings is beyond the scope of our general home inspection. If you are concerned or believe that these conditions may exist in a nonvisible or concealed area, we recommend that you have this home further examined by a qualified contractor or environmental hygienist prior to the end of your contingency period.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



WALL/ CEILING MATERIAL: SHEETROCK

Comments:

(1) A representative sampling for moisture was preformed at accessible interior walls using a moisture meter. (areas prone to moisture, such as kitchens, bathrooms, below grade walls, exterior walls with doors/windows). An elevated moisture was not detected at the time of the inspection.

(2) Determining if damage, the presence of organic growths, moisture or wood rot behind walls, floors and ceiling coverings is beyond the scope of our general home inspection. If you are concerned or believe that these conditions may exist in a nonvisible or concealed area, we recommend that you have this home further examined by a gualified contractor or environmental hygienist prior to the end of your contingency period.

(3) A WORD ABOUT PHOTOS: The photos in this report and their associated captions are included as a sampling of the conditions inspected. The photos are intended to clarify selected issues, but are NOT intended to imply their relative importance. Client(s) is advised that NOT all defects will be supported with photos and that NOT all photos taken will be used in the report. If similar defects are found at several locations throughout the property, only a representative number of photos may be shown in this report. Repairs should not be limited to only those areas, but at all instances of the defect(s). Sometimes it is not possible to take a photograph of a defect due to location, lighting, or other obstructions. Numerous photos may be taken of a property but not all will necessarily be included with a corresponding comment in the report. Only a sample number of photos are used and it's MOST important to use and go off the written comment and written information provided in your report. Please reach out to your inspector to request additional photos of an area or item you would want included.

(4) We did not test the property for asbestos. Testing for asbestos is out of the scope of a general home inspection and was not done by this company at the time of the inspection. If your concerned that the this property may contain

IN NI NP RR IO Items

IN NI NP RR IO Items

asbestos, we recommend that you have the property tested for asbestos prior to the end of your contingency period by a qualified licensed contractor.




6.1 CEILINGS

Comments:

(1) The ceiling has typical cosmetic wear. You may wish to view this for yourself and have necessary repairs made by a qualified person.

(2) Patching was noted at the ceiling in several areas. We recommend asking the seller if they have knowledge of the repair or cause.



6.1 Item 1(Picture)



6.2 WALLS

Comments:

(1) Base boards are separating from the wall at several areas throughout the house. We recommend replacing where needed by a qualified person.



6.2 Item 1(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items





6.2 Item 2(Picture)

(2) Patching was noted at the walls in several areas. We recommend asking the seller if they have knowledge of the repair or cause.



6.2 Item 3(Picture)






IN NI NP RR IO Items

IN NI NP RR IO Items

(3) Hairline cracking was observed at several locations. These hairline cracks are likely due to material shrinkage or settlement of the structure. We recommend prep and paint by a qualified licensed painter.



6.2 Item 5(Picture)



6.2 Item 6(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items

(4) Damage floor trim was noted next to the dishwasher. We recommend repairs by a licensed qualified contractor.



6.2 Item 7(Picture)

(5) Due to stored personal items not all areas throughout the property were visible and accessible at the time of the inspection. The slab and other areas were obstructed from view and could not be inspected. The home inspector does not move personal items, panels, furniture, equipment, plant life, soil, debris, ect. that obstructs their access or visibility. We recommend that you conduct a careful evaluation during your final walk-through or prior to the end of your contingency period to ensure that there are no hidden defects. All doors, windows, and outlets should be tested and verified for proper operation prior to the end of your contingency period by a qualified person. If any damage is observed we recommend asking the seller about it. We recommend that any damage found be repaired or replaced by a qualified licensed contractor in the appropriate trade.

(6) The walls have typical cosmetic wear. You may wish to view this for yourself and have necessary repairs made as needed by a qualified person.



6.3 FLOOR COVERINGS

Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

(1) Carpets throughout the house are dirty. We recommend having them professional cleaned or replaced by a qualified licensed flooring contractor.



6.3 Item 1(Picture)

(2) There is a cracked floor tile observed in the kitchen. We recommend necessary repairs or replacement by a qualified licensed flooring contractor.



6.3 Item 2(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items



6.3 Item 3(Picture)

(3) There is damaged wood flooring observed in the family room. We recommend necessary repairs or replacing by a qualified licensed flooring contractor.



6.3 Item 4(Picture)






IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



6.4 STEPS, STAIRWAYS, RAILINGS

Comments:

The stair/landing railing is loose. This is a safety hazard and corrections are needed. We recommend necessary repairs for safety by a qualified licensed contractor.



6.4 Item 1(Picture)




6.5 COUNTERS AND CABINETS (REPRESENTATIVE NUMBER)

Comments:

Due to stored personal items such as towels, clothing, personal items, hygiene and/or cleaning products, a full evaluation of the cabinets and closets could not be made. We recommend that you carefully inspect all cabinets and closets prior to the end of your contingency period or during your final walk through. The home inspector does not move personal items, panels, furniture, equipment, plant life, soil, debris, ect. that obstructs their access or visibility. If any damage is observed we recommend asking the seller about it. We recommend that any damage found be repaired or replaced by a qualified licensed contractor in the appropriate trade..



6.5 Item 1(Picture)



6.6 DOORS (REPRESENTATIVE NUMBER) Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

(1) Several bedroom doors rub on the carpet. This can wear at the carpet in this area, and also prevents the proper air exchange when the heating/cooling systems are on. There should be a one inch clearance at the bottom of the door. We recommend necessary corrections by a qualified person.



6.6 Item 1(Picture)

(2) The door latching hardware is not installed on the master bedroom doorframe. We recommend service or replacement by a qualified person.

(3) Several door upstairs doorframes are damaged. We recommend replacement by a qualified contractor.



6.6 Item 2(Picture)



6.7 INFRARED CAMERA INSPECTION FINDINGS Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

(1) Infrared Camera Thermal Photos.



6.7 Item 1(Picture)



6.7 Item 2(Picture)



6.7 Item 3(Picture)


IN NI NP RR IO Items

IN NI NP RR IO Items



6.7 Item 4(Picture)

(2) An infrared (thermal imaging) scan was performed throughout the property at the time of the inspection using a hand held infrared (thermal imaging) inspection camera. No anomalies were found at the time of the inspection using this camera.



6.8 SAFETY GLASS (INTERIOR)

6.9 INTERIORS - OTHER

Comments:

(1) Determining the presence of organic growths, moisture or wood rot behind any walls, floors and ceiling coverings is beyond the scope of our general home inspection. We recommend further evaluation by a qualified licensed contractor or a environmental hygienist prior to the end of your contingency if you are concerned.

(2) MAINTENANCE RECOMMENDATION: We recommend re sealing (caulking or grouting) around all sink to counter top junctions and backsplash to countertop junctions, and around all bathroom shower pan(s), curb(s), tub/ shower floor junctions, and adjacent walls throughout the house or where needed by a qualified person to help prevent moisture intrusion in these areas.

(3) MAINTENANCE RECOMMENDATION: We recommend having the property professionally cleaned prior to moving in by a licensed cleaning company.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report. Cosmetic deficiencies are considered normal wear and tear and are not reported.

7. Plumbing System

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials unless otherwise agreed upon. Determining whether shower pans are watertight is beyond the scope of the inspection.

Laundry Note: Washers and dryers are not moved or tested during the inspection. The washer drain line and the dryer vent duct are not tested. Best practices for washer and dryer installation include the following recommendations: Use braided metallic water hoses to reduce the potential of leaks at the washing machine. Use flexible metal dryer vent connector. Use a half inch appliance connector and gas valve for all newer gas dryers. Installation of a drain pan under the washing machine with a drain pipe terminating at the exterior.

Underground Gas Pipe Note: Determining if the below ground gas pipes leak is beyond the scope of a home inspection. If concerned we recommend further evaluation of all underground gas piping by a licensed plumbing contractor prior to the end of your contingency period. Note: While the inspector attempts to discover gas leaks at the accessible gas fittings and appliances while using a gas leak detector, some leaks can go undetected.

Home inspectors <u>do not</u> operate (turn) any water supply shut off valves at any property such as angle stops (the type under sinks and toilets), laundry hose spigots, water heater supply valves, or main water shut off valves at the meter. Home inspectors <u>do not</u> test clothes washer drains or stand pipes, or flood test the over-flow drains at tubs and sinks in accordance with industry standards of practice. If you have questions about these exclusions, please contact your home inspector.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



7.0 PLUMBING CONDO

GAS DISTRIBUTION: RIGID IRON PIPE, PARTIALLY VISIBLE

Comments:

This inspection is being conducted on a condominium unit. The inspection is limited to the components that are inside of the unit only. Plumbing components that are located beyond the interior of the condominium, such as common drain and supply pipes, are not evaluated as part of this inspection and are the responsibility of the HOA. If you have any concerns about any plumbing components outside the interior of this unit we recommend contacting the HOA.



7.1 DRAIN, WASTE, AND VENT SYSTEMS

PLUMBING WASTE (OBSERVED INSIDE THE HOME): ABS, PARTIALLY VISIBLE WASHER DRAIN SIZE: 2" DIAMETER

Comments:

At the time of the inspection we evaluated all drain pipes by running water through every drain that has an active fixture while observing its draw and watching for blockages or slow draining. Kitchen and bathroom fixtures were tested for an extended period of time during the inspection. We did not test the laundry stand pipe if a washing

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items

machine is connected. A video-scan of the drains and main line can only help determine the actual condition(s) of these drain pipes. We recommend having a sewer camera inspection conducted to help determine the condition of the pipes prior to the end of your contingency period.



7.2 WATER SUPPLY, DISTRIBUTION SYSTEMS


WATER SOURCE: PUBLIC

PLUMBING WATER DISTRIBUTION (INSIDE THE HOME): COPPER, PARTIALLY VISIBLE



7.3 WATER PRESSURE/ REGULATOR

WATER PRESSURE (PSI): COULD NOT DETERMINE




7.4 HOSE SPIGOT(S)

Comments:

The rear hose spigot has a hose that could not be made to come off as it appears to be rusted on. We recommend having the hose removed by a qualified person.



7.4 Item 1(Picture)



7.5 GAS/ FUEL STORAGE AND DISTRIBUTION SYSTEMS Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

(1) The gas piping in the attic is loose/ not properly secured as required. We recommend necessary repairs by a qualified licensed plumber.



7.5 Item 1(Picture)

(2) A gas leak test was conducted at accessible gas fittings and appliances using a gas leak detector. There were no gas leaks detected at the time of the inspection.



7.5 Item 2(Picture)



7.6 SINK(S) Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

(1) There are older one piece angle stop valve(s)/ supply line(s) observed at the sinks. These one piece angle stop valve(s)/ supply line(s) have a reputation to corrode from the inside and possible fail. A white power substance or corrosion/ calcification is observed at the one piece angle stop valve(s)/ supply line(s). We recommend that these one piece angle stop valve(s)/ supply line(s) be replaced by a qualified licensed plumber as an upgrade.



7.6 Item 1(Picture)

(2) Some of the sink angle stop valves are observed with calcium deposits on them. Calcium deposits can corrode or deteriorate these valves and cause potential leaks. We recommend replacing all calcified angle stop valves by a qualified licensed plumber to help prevent leaks.



7.6 Item 2(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items

(3) There is an older one piece angle stop valve/ supply line observed at the toilets. These one piece angle stop valve/ supply lines have a reputation to corrode from the inside and possible fail. A white power substance or corrosion/ calcification is observed at the one piece angle stop valves/ supply lines. We recommend that this one piece angle stop valves/ supply lines be replaced as need by a qualified licensed plumber as an upgrade.



7.6 Item 3(Picture)

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. The water supply and waste line piping that is concealed within inaccessible areas such as covered walls and concrete slab floors was not evaluated.Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

8(A) . Hall Bathroom Downstairs

The bathroom(s) and it's related components were inspected and appeared to be functioning/ operating as intended at the time of the inspection unless other wise commented on in the appropriate bathroom section(s).

MAINTENANCE RECOMMENDATION: We recommend re sealing (caulking or grouting) around all sink to counter top junctions and backsplash to countertop junctions, and around all bathroom shower pan(s), curb(s), tub/ shower floor junctions, and adjacent walls throughout the house or where needed by a gualified person.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



Comments:

MAINTENANCE RECOMMENDATION: We recommend re sealing (caulking or grouting) around all sink to counter top junctions and backsplash to countertop junctions, and around all bathroom shower pan(s), curb(s), tub/ shower floor junctions, and adjacent walls throughout the house or where needed by a qualified person to help prevent moisture intrusion in these areas.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The bathroom(s) were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving personal property, furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that gualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report. Cosmetic deficiencies are considered normal wear and tear and are not reported.


8(B) . Hall Bathroom Upstairs

The bathroom(s) and it's related components were inspected and appeared to be functioning/ operating as intended at the time of the inspection unless other wise commented on in the appropriate bathroom section(s).

MAINTENANCE RECOMMENDATION: We recommend re sealing (caulking or grouting) around all sink to counter top junctions and backsplash to countertop junctions, and around all bathroom shower pan(s), curb(s), tub/ shower floor junctions, and adjacent walls throughout the house or where needed by a qualified person.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



8.0.BTUB/ SHOWER ENCLOSURE

Comments:

(1) The tub diverter did not operate properly when tested. This is likely due from hard water deposit build up on the tub spout mechanism. We recommend necessary repairs or replacement by a licensed plumber.



8.0.B Item 1(Picture)


(2) The shower head arm is loose in the wall. This condition could allow water to enter behind the tub/shower wall and could put unwanted stress on the water supply pipes. We recommend necessary repairs by a qualified licensed plumber.



8.1.B GFCI OPERATION

Comments:

There is more than one GFCI receptacle installed on the bathroom circuit. This condition is not a hazard but can cause confusion to reset if one trips. Only one GFCI is required to protect all of the receptacles past the GFCI. We recommend necessary corrections by a qualified licensed electrician.



8.2.B EXHAUST FAN Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

The bathroom vent fan is dirty/ clogged with debris. We recommend having the bathroom vent fan cleaned by a qualified person.



8.2.B Item 1(Picture)



8.3.B BATHROOM OTHER

Comments:

MAINTENANCE RECOMMENDATION: We recommend re sealing (caulking or grouting) around all sink to counter top junctions and backsplash to countertop junctions, and around all bathroom shower pan(s), curb(s), tub/ shower floor junctions, and adjacent walls throughout the house or where needed by a qualified person to help prevent moisture intrusion in these areas.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The bathroom(s) were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving personal property, furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report. Cosmetic deficiencies are considered normal wear and tear and are not reported.

8(C) . Master Bathroom

The bathroom(s) and it's related components were inspected and appeared to be functioning/ operating as intended at the time of the inspection unless other wise commented on in the appropriate bathroom section(s).

MAINTENANCE RECOMMENDATION: We recommend re sealing (caulking or grouting) around all sink to counter top junctions and backsplash to countertop junctions, and around all bathroom shower pan(s), curb(s), tub/ shower floor junctions, and adjacent walls throughout the house or where needed by a qualified person.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items




Comments:

(1) The left sink stopper was inoperable when tested. We recommend necessary repairs or replacement by a qualified person.



8.0.C Item 1(Picture)

(2) Several sink faucet leak at the handles when operated. We recommend necessary repairs or replacement by a gualified licensed plumber.



8.1.C FLOOR

Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

Carpets installed in bathrooms can trap moisture and urine, substances that can cause structural damage and health problems. Since this condition is conducive to mold growth, we advise removal of carpet from the master bathroom.



8.1.C Item 1(Picture)



8.2.C BATHROOM OTHER Comments:

MAINTENANCE RECOMMENDATION: We recommend re sealing (caulking or grouting) around all sink to counter top junctions and backsplash to countertop junctions, and around all bathroom shower pan(s), curb(s), tub/ shower floor junctions, and adjacent walls throughout the house or where needed by a qualified person to help prevent moisture intrusion in these areas.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The bathroom(s) were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving personal property, furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report. Cosmetic deficiencies are considered normal wear and tear and are not reported.

9. Laundry

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items




9.0 WASHING MACHINE/ DRYER CONNECTION(S)

DRYER POWER SOURCE: 220 VOLT ELECTRIC AND GAS, 220 VOLT ELECTRIC (3 PRONG)

Comments:


(1) There is a three prong 220 volt receptacle installed for the dryer. Most new electric dryers require a four prong receptacle. If you install an electric dryer, you may need to upgrade the receptacle or the dryer power cord. We recommend necessary corrections by a qualified licensed electrician.


(2) MAINTENANCE RECOMMENDATION: Washer hoses are a common source of flooding in a home. Prior to connecting the washing machine we recommend installing new braided steel washer hoses to help reduce leaks caused by failed hoses. If any hoses are left in the house they should be replaced. The washing machine and dryer are not part of our general home inspection.



9.0 Item 1(Picture)

(3) **SAFETY TIP** : We recommend capping the unused dryer gas supply pipe until a dryer is installed for safety.





IN NI NP RR IO Items

Smyth



9.1 CLOTHES DRYER VENT

DRYER VENT: FLEXIBLE METAL, METAL

Comments:

(1) We recommend having the dryer vent cleaned by a qualified person.

(2) The dryer vent is to long. The dryer vent maximum length of a clothes dryer duct should not exceed 25'. Any 90-degree turns in the vent reduce this 25-foot number by 5 feet. The current duct appears to be to long or have too many bends. Improper installation can be a fire hazard. We recommend necessary corrections by qualified person.



9.1 Item 1(Picture)

9.2 LAUNDRY ROOM VENT



9.3 LAUNDRY OTHER

Comments:

The clothes washer and dryer are not part of our general inspection and were not inspected or commented on. If concerned about there serviceability and functionality we recommend further evaluation by a qualified licensed appliance contractor prior to the end of your contingency period.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The laundry room/ area inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving personal property, furniture, washing machine/ dryer and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report. Cosmetic deficiencies are considered normal wear and tear and are not reported.

10. Fireplaces/ Chimneys

This inspection of the fireplace/ chimney is limited to the readily visible portions only. The inner reaches of a chimney flue are not visually accessible and the view from the top or bottom is not adequate to discover possible deficiencies or damage with in our general home inspection. We recommend that a National Fire Protection Association (NFPA) 211 Standard, Level II inspection by a qualified licensed professional be preformed prior to the end of your contingency period. They can use specialized tools, testing procedures, mirrors, and video cameras to thoroughly evaluate the fireplace system. We do not light the gas or start a fire, or check for proper drafting.

We recommend that all fireplaces be cleaned and inspected by a qualified licensed person prior to using and on a regular basis to insure safe operation.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items




10.0 CHIMNEY(S)

FIRE PLACE TYPES: FACTORY BUILT, CONCRETE LOG KIT, SWITCHED ACTIVATED GAS ONLY NUMBER OF FIREPLACE(S): ONE

Comments:

We recommend having the fireplace and chimney cleaned and inspected by a licensed chimney sweep for safety prior to using.




10.1 FIREPLACE(S)

10.2 HEARTH/ MANTLE

Comments:

The hearth at the front of the fireplace is missing/ of inadequate size/ or an improper material. This condition does not comply with current building and fire and safety requirements. We recommend installation of a properly sized hearth by a qualified licensed contractor.



10.2 Item 1(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items



10.2 Item 2(Picture)



10.3 OPERATING CONTROLS

Comments:

The vented gas log fireplace did not light when tested from the wall switch. The flame is controlled by the wall switch. The gas pilot may have been not on at the time of the inspection. We do not restore fuel or power to appliances that are shut off; therefore, our review is limited. Most utility companies, upon request, light pilots. We recommend further evaluation by a qualified licensed contractor and necessary repairs as needed.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only


The fireplace was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

11. Detectors, Safety, Security

÷

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



11.0 SMOKE DETECTORS

Comments:

We recommend installing additional smoke detectors where needed to comply with current fire and safety standards and regulations as a safety upgrade.



11.0 Item 1(Picture)



11.1 CARBON MONOXIDE DETECTOR(S)

Comments:

(1) Photo of carbon monoxide detector(s).



11.1 Item 1(Picture)

(2) The quantity of Carbon Monoxide detectors that are required to be installed varies with each house. Larger houses, or those with multiple levels are required to have more CO detectors. A Carbon Monoxide detector is required on each level of a multi-level

IN NI NP RR IO Items

IN NI NP RR IO Items

house and adjacent to each cluster of bedrooms. We recommend installing additional Carbon Monoxide detectors where needed.



11.2 SAFETY - OTHER

Comments:

(1) All smoke detector should be tested upon moving into home, and every six months or per manufactures instructions. Smoke detectors should be replaced when they reach 10 years of age as their sensor becomes less effective over time or per manufactures instructions.

(2) All carbon monoxide detectors should be tested upon moving into home, and every six months or per manufactures instructions. Carbon monoxide detectors should be replaced per manufactures instructions.



11.3 FIRE SPRINKLERS

Comments:

There is a fire sprinkler system installed in the house and was not inspected by this company at the time of the home inspection. Inspecting fire sprinkler systems is beyond the scope of our general home inspection. We recommend having the fire sprinkler system inspected by a qualified licensed contractor prior to the end of your contingency period.



11.4 SECURITY SYSTEM

Comments:

There is a security system installed in the house and was not inspected by this company at the time of the home inspection. Inspecting security systems is beyond the scope of a general home inspection. We recommend having the security system inspected by a qualified licensed contractor prior to the end of your contingency period.

IN NI NP RR IO Items

12. Heating Equipment

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues: the interior of ducts; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.

Note: A limited visual inspection can not adequately evaluate the heat exchanger for cracks and holes. Most areas of the heat exchanger are not visible without dismantling the furnace. Dismantling the furnace is beyond the scope of our general home inspection. Evaluation of the heat exchanger is expressly excluded. Evaluating the adequacy, efficiency, or even distribution of air throughout the home is not part of the inspection. Thermostats are not checked for calibration or programmable features, interior of the ducts are not inspected for cleanliness and if concerned about the cleanliness we recommend having them checked and cleaned by a licensed HVAC contractor prior to the end of your contingency period.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



HEAT TYPE: FORCED AIR NUMBER OF HEAT SYSTEMS (EXCLUDING WOOD): ONE ENERGY SOURCE: NATURAL GAS AGE OF HEATER: NEW/ LESS THAN 1 YEAR

Comments:

(1) The furnace was tested and was functional/ operated at the time of the inspection.




12.0 Item 1(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items

(2) Infrared Thermal photo of the furnace(s) being tested.



12.0 Item 2(Picture)




12.1 THERMOSTAT(S)

Comments:

The thermostat was operational when used to operate the HVAC system at the time of the inspection. Programmable thermostats are not adjusted and no testing is done to check the accuracy or programmed settings of the thermostat. If concerned we recommend verifying proper operation of the programmable settings prior to the end of your contingency period by a qualified person.





IN NI NP RR IO Items

IN NI NP RR IO Items



12.1 Item 2(Picture)



12.2 VENTS AND FLUES (HEATING SYSTEM)

12.3 DISTRIBUTION SYSTEMS (INCLUDING FANS, PUMPS, DUCTS, INSULATION, FILTERS, REGISTERS)

DUCTWORK: INSULATED

FILTER TYPE: FILTER(S) ARE DIRTY. WE RECOMMEND REPLACING.

Comments:

The air filter(s) for the HVAC system is dirty. We recommend recommend replacing by a qualified person.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

13. Cooling Equipment

The home inspector shall observe: Central air conditioning and permanently installed cooling systems including: Cooling and air handling equipment; and Normal operating controls. Distribution systems including: Fans, pumps, ducts and piping, with associated supports, dampers, insulation, air filters, registers, fan-coil units; and The presence of an installed cooling source in each room. The home inspector shall describe: Energy sources; and Cooling equipment type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance The home inspector is not required to: Observe window air conditioners or operate cooling systems when weather conditions or other circumstances may cause equipment damage; Observe non-central air conditioners; or Observe the uniformity or adequacy of cool-air supply to the various rooms.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only


IN NI NP RR IO Items

13.0 COOLING EQUIPMENT COOLING EOUIPMENT TYPE: AIR CONDITIONER NUMBER OF A/C UNITS: ONE

CONDENSER AGE: NEW, LESS THAN 1 YEAR

Comments:

(1) Photo of the A/C unit(s).



13.0 Item 1(Picture)



13.0 Item 2(Picture)

IN NI NP RR IO Items




IN NI NP RR IO Items

(2) An ambient air test was performed by using a thermal camera on the AC system to determine if the difference in temperatures of the supply and return air were between 14 degrees and 22 degrees which indicates that the AC system is cooling as intended.

The air supplied to the room was measured around 36 degrees.

The air returning to the system (return) was measured at **56 degrees**.

This indicates that the range in temperature drop is normal. This is not an exhaustive test and cannot predict the performance of the AC systems on extremely hot or humid days.



13.0 Item 3(Picture)



13.0 Item 4(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items

(3) The AC unit electrical conduit is not secured to the wall as required. We recommend having the AC unit conduit secured to the wall by a qualified person.



13.0 Item 5(Picture)



IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed HVAC contractor would discover (Heating, Ventilation, and Air Conditioning). Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

14. Ventilation and Insulation

The home inspector shall observe: Insulation and vapor retarders in unfinished spaces; Ventilation of attics and foundation areas; Kitchen, bathroom, and laundry venting systems; and the operation of any readily accessible attic ventilation fan, and, when temperature permits, the operation of any readily accessible thermostatic control. The home inspector shall describe: Insulation in unfinished spaces; and Absence of insulation in unfinished space at conditioned surfaces. The home inspector shall: Move insulation where readily visible evide



unfinished space at conditioned surfaces. The home inspector shall: Move insulation where readily visible evidence indicates the need to do so; and Move insulation where chimneys penetrate roofs, where plumbing drain/waste pipes penetrate floors, adjacent to earth filled stoops or porches, and at exterior doors. The home inspector is not required to report on: Concealed insulation and vapor retarders; or Venting equipment that is integral with household appliances.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



Comments:


(1) Photo of the insulation.



14.0 Item 1(Picture)

(2) Some of the batt insulation has been moved in the attic space. This insulation was not put back into position where needed. We recommend having the insulation distributed properly/ put back into place to improve the thermal efficiency of the house by a qualified person.





IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



14.0 Item 3(Picture)

(3) Insulation was noted to be in contact with several recessed lights in the attic area. This is a safety/ fire hazard. We recommend removal/ necessary corrections by a qualified person.

(4) The attic space access hatch cover is not insulated. We recommend insulating the attic access hatch cover to reduce unwanted heat loss/gain by a qualified person.


14.1 VENTALATION OF THE ATTIC SPACE

14.2 WHOLE HOUSE FAN

Comments:

The whole house fan did operate when tested at the time of the inspection.





IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The insulation and ventilation of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Venting of exhaust fans or clothes dryer cannot be fully inspected and bends or obstructions can occur without being accessible or visible (behind wall and ceiling coverings). Only insulation that is visible was inspected. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

15. Structural Components

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector




is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons. Note: Much of the home structure is hidden behind exterior and interior roof, floor, wall, and ceiling coverings, or is buried underground. Because the General Home Inspection is limited to visual and non-invasive methods, this report may not identify all structural deficiencies. Identification of portions of the wall structure not directly visible requires logical assumptions on the part of the Inspector that are based on the Inspectors past experience and knowledge of

Upon observing indications that structural problems may exist that are not readily visible, or the evaluation of which lies beyond the Inspector's expertise, the inspector may recommend evaluation or testing by a specialist that may include invasive measures, which would require homeowner permission.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



common building practices.

15.0 STRUCTURE (CONDO)

Comments:

This inspection was performed on a Condo. It includes the interior of the unit only. It specifically excludes any crawlspaces, if present. A condo inspection specifically excludes an evaluation of the wood, structure, or foundation.



1ST LEVEL FLOOR STRUCTURE: SLAB

Comments:

The concrete slab throughout the property was not visible to inspect. Home Inspectors do not move stored items or lift floor coverings which may conceal cracks or other concealed defects that the inspector cannot see. This should not deter you from further evaluation by a gualified licensed foundation contractor or structural engineer prior to the end of your contingency period if concerned about the slab. It would be your (clients) responsibility to arrange this and for lifting or removing of the flooring.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

16. Built-In Kitchen Appliances

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. Inspection of built-in appliances is limited. It does not include dismantling and inspection of interval parts. The home inspection is not required to check the check of the second second



internal parts. The home inspection of built-in appliances is limited. It does not include dismanting and inspection of for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable, or determine the effectiveness or life remaining of any built-in appliances.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items




16.0 MICROWAVE (BUILT-IN)

Comments:

(1) Photo of microwave being tested.

The built in microwave was tested with a microwave testing device and was functional at the time of the inspection. This is not an exhaustive test, and does not predict the performance of the microwave.



16.0 Item 1(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items

(2) The built in microwave was installed too close to the cooktop burners. This condition could cause damage to the plastic covering and the electronic control panel due to excessive heat. We recommend replacing the microwave with a low-profile microwave or relocating it which would allow at least 18 inches of clearance between the bottom of the microwave and the cooktop burners. Lower clearances may be allowed per manufacturers listing.



16.0 Item 2(Picture)



16.1 DISHWASHER

Comments:

(1) Infrared Thermal photo of the dishwasher being tested.


The dishwasher was tested and functioned properly at the time of the inspection. This is not an exhaustive test and does not verify the cleaning efficiency of the dishwasher.



16.1 Item 1(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items



16.1 Item 2(Picture)

(2) An air gap device was not installed for the dishwasher. An air gap device is required to prevent dirty water from being sucked back into the water supply. We recommend installation of an air gap device by a qualified license appliance contractor or plumber.



16.1 Item 3(Picture)

(3) The dishwasher kick plate is missing. We recommend replacing by a qualified person.



16.2 FOOD WASTE DISPOSER

Comments:

The food waste disposer was tested and functioned properly at the time of the inspection. This is not an exhaustive test and does not verify the efficiency of the unit.



16.3 RANGE HOOD/ VENT

RANGE HOOD/ EXHAUST TYPE: RE-CIRCULATE


Comments:

The range exhaust vent was tested and was functional at the time of the the inspection. This is not an exhaustive test, and does not evaluate the performance or effectiveness of the unit.

IN NI NP RR IO Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



16.4 RANGE/ OVEN

RANGE/ OVEN: GAS

Comments:

(1) Infrared Thermal photo of the oven being tested.

The oven was tested and was functional at the time of the inspection. This test is not exhaustive and does not confirm the performance, accuracy, or effectiveness of the oven.



16.4 Item 1(Picture)


(2) An anti tip bracket was not installed at the range. This bracket prevents the range from tipping forward which could cause the range to fall over. We recommend installation of an anti tip bracket by a qualified person for safety and to help prevent injury.




16.4 Item 2(Picture)

IN NI NP RR IO Items

IN NI NP RR IO Items



16.4 Item 3(Picture)



16.5 REFRIGERATOR

Comments:

(1) Refrigerators built in or not are not part of our general home inspection and are not inspected or commented on. If concerned about its serviceability and functionality we recommend further evaluation by a qualified licensed appliance contractor prior to the end of your contingency period.



16.5 Item 1(Picture)

(2) I could not identify or inspect the outlet or water shut off valve for the refrigerator. I do not move refrigerators in order to access the outlet or water shut off valve. Moving refrigerators is out of the scope of a home inspection are not moved to inspect the walls/floors/other components behind them. If concerned we recommend verifying that the outlet and water shut off valve is operational, not corroded and not leaking prior to the end of your contingency period.

IN NI NP RR IO Items

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified licensed contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

17. Gas, Electric, Water Shut-Off Locations

Home inspectors <u>do not</u> operate (turn) the main water supply shut off valve or the main gas shut off valve in accordance with industry standards of practice. If you are concerned about the functionality of these valves we recommend contacting a licensed plumber prior to the end of your contingency period for review. If you have questions about these exclusions, please contact your home inspector.

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, IO= Information Only

IN NI NP RR IO Items



17.0 MAIN GAS SHUT-OFF VALVE

Comments:

(1) The main gas shut off valve is located at the gas meter at the left exterior side of the property (facing front).



17.0 Item 1(Picture)

(2) The gas meters are not labeled for the individual units and identifying the exact meter for this unit is outside the scope of this inspection. We recommend inquiry with the Home Owners' Association, SDG&E or the seller.

17.1 MAIN ELECTRICAL PANEL

Comments:

The Main Electric panel was not located. We recommend asking the seller to verify the location and we recommend having it inspected prior to the end of your contingency period by this company or by a licensed electrician.



17.2 MAIN WATER SHUT-OFF Comments:

IN NI NP RR IO Items

IN NI NP RR IO Items

The main water shut off valve is located in the garage.



17.2 Item 1(Picture)



17.3 SUB ELECTRICAL PANEL(S)

Comments:

The sub-panel is located in the garage.



17.3 Item 1(Picture)

IN NI NP RR IO Items

General Summary



The Property Inspection Pros

WWW.TPIPS.COM jduncan@tpips.com Cell: 760-525-5340 Certified Professional Inspector

Customer John Smyth

Address 1234 Main Street Santee CA 92071

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling;** or **warrants further investigation by a specialist,** or **requires subsequent observation.** This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

2. Exterior

2.2 GRADING AND DRAINAGE (WITH RESPECT TO ITS EFFECT ON THE BUILDING)

Repair or Replace

(2) The rear platform has been built at the same level as the interior slab/ floor. The ideal building will have interior floors that will be several inches higher than the exterior grade. This property does not meet this ideal requirement. Repairs may be need to prevent damage/moisture intrusion. We recommend further evaluation and necessary repairs by a licensed landscaping contractor.

2.3 WALL CLADDING FLASHING AND TRIM

Repair or Replace

(1) There is damaged/ deteriorated stucco observed at several areas. We recommend necessary repairs where needed by a licensed stucco contractor.

2.4 DOORS (EXTERIOR)

Repair or Replace

A pet door is present at the exterior garage door. These modifications can cause damage to the door by letting in rain. These modifications can also reduce the security of the door by making it easier for someone to enter or reach inside and unlock the door. We recommend sealing the door or replacing the

door by a qualified person

2.7 DRIVEWAYS, PATIOS, WALKWAYS (HARDSCAPE)

Repair or Replace

There is missing, cracked and damaged mortar between several stones at the rear patio area. We recommend necessary repairs by a licensed concrete contractor.

3. Electrical System

3.3 BRANCH CIRCUIT CONDUCTORS/ WIRING

Repair or Replace

(1) Wires for some lighting fixtures in the attic space were observed to be unsecured. We recommend necessary corrections by a qualified licensed electrician.

3.6 SWITCHES

Repair or Replace

The stairwell three-way light does not light the bottom of the stairs fully. This is a safety concern and corrections are needed. We recommend necessary repairs by a qualified licensed electrician.

3.13 EXTERIOR LIGHTING

Repair or Replace

(1) The exterior light fixtures were not sealed where the fixture meets the wall. This condition could allow moisture intrusion in this area. We recommend sealing exterior light fixtures where they meet the wall by a qualified person.

4. Garage

4.1 GARAGE VEHICLE DOOR OPENER(S)

Inspected

(2) As of July 1, 2019 all garage door openers are required to have a battery back up that is designed to operate when activated due to an electrical outage. Replacement of the garage doors connected to an automatic opener requires updating to a battery backup type. Verification of compliance is beyond the scope of this inspection. Client is advised to verify compliance and update if needed.

(4) Due to the high number of garage door openers that fail to auto-reverse when testing the garage door openers pressure-activated auto-reverse feature which could cause severe damage to the garage door and its related components when it fails to auto-reverse, we did not test the garage door openers pressure-activated auto-reverse feature at the time of the inspection. We recommend having the garage door(s) pressure-activated auto-reverse feature tested prior to the end of your contingency period by a qualified licensed garage door contractor.

(5) The emergency release cord is missing. The emergency release cord is a safety item that is required to be mounted with the handle no more than 6 feet from the floor. We recommend correction by a qualified person.

4.2 GARAGE CEILING

Repair or Replace

(2) The ceiling has typical cosmetic wear. You may wish to view this for yourself and have necessary repairs made by a qualified person.

(3) There are several holes/ damage observed at the garage ceiling. We recommend necessary repairs where needed by a qualified licensed contractor.

4.3 GARAGE WALLS (INCLUDING FIREWALL SEPERATION)

Inspected

(1) Due to occupants personal items, not all areas of the property were visible and accessible at the time of the inspection. Several windows, doors, outlets, walls, flooring, and other areas were obstructed from view and could not be inspected. The home inspector does not move personal items, panels,

furniture, equipment, plant life, soil, debris, ect. that obstructs their access or visibility. We recommend that you conduct a careful evaluation during your final walk-through or prior to the end of your contingency period to ensure that there are no hidden defects. All doors, windows, and outlets should be tested and verified for proper operation prior to the end of your contingency period by a qualified person. If any damage is observed we recommend asking the seller about it. We recommend that any damage found be repaired or replaced by a qualified licensed contractor in the appropriate trade.

4.5 FIRE-RATED DOOR

Inspected

The door between the house and garage did not have a Fire Rating Certificate or Plate. Without a plate, I could not confirm whether the door meets fire code safety requirements. We recommend further evaluation by a licensed door contractor. The "fire door" is required to meet one of the following characteristics:1-3/8 inch thick solid wood, 1-3/8 inch thick steel shell door with Honeycomb core, Firerated (with certificate plate). If the door is not rated as a fire door we recommend replacing by a qualified licensed door contractor for safety.

4.6 FIRE-DOOR CLOSING DEVICE

Repair or Replace

(1) The door to the garage has a door stopper installed at the bottom of the door. The door stopper defeats the auto closer, which is required. We recommend removal of the door stopper to maintain the integrity of the fire wall and fire door.

5. Water Heater

5.0 MAIN WATER HEATER (CONTROLS)

Repair or Replace

(3) The gas supply pipe at the water heater did not contained a drip leg/ sediment trap. This may have been standard at the time of installation but now is highly recommended. The purpose of a drip leg is to prevent sediment/ debris from entering and clogging the water heater gas valve which could cause the water heater to shut down. We recommend having a drip leg installed by a qualified licensed plumber.
(5) A leak pan is not installed under the water heater. We recommend installing a leak pan under the

water heater by a qualified licensed plumber.

(6) The water heater is an older unit/ 10 plus years, and repairs or even failure can be expected. Based on manufacture's statistics the average life of a water heater is 7-10 years. We recommend replacing the water heater by a qualified licensed plumber.

(7) The water heater gas pipe fittings appear to have white teflon tape installed on them. This is non standard. White teflon tape is intended for use on water pipe fittings. We recommend necessary corrections by a qualified licensed plumber.

6. Interiors

6.0 INTERIORS (GENERAL COMMENTS)

Information Only

(4) We did not test the property for asbestos. Testing for asbestos is out of the scope of a general home inspection and was not done by this company at the time of the inspection. If your concerned that the this property may contain asbestos, we recommend that you have the property tested for asbestos prior to the end of your contingency period by a qualified licensed contractor.

6.1 CEILINGS

Inspected

(1) The ceiling has typical cosmetic wear. You may wish to view this for yourself and have necessary repairs made by a qualified person.

6.2 WALLS

Repair or Replace

(1) Base boards are separating from the wall at several areas throughout the house. We recommend replacing where needed by a qualified person.

(2) Patching was noted at the walls in several areas. We recommend asking the seller if they have knowledge of the repair or cause.

(3) Hairline cracking was observed at several locations. These hairline cracks are likely due to material shrinkage or settlement of the structure. We recommend prep and paint by a qualified licensed painter.(4) Damage floor trim was noted next to the dishwasher. We recommend repairs by a licensed qualified contractor.

6.3 FLOOR COVERINGS

Repair or Replace

(1) Carpets throughout the house are dirty. We recommend having them professional cleaned or replaced by a qualified licensed flooring contractor.

(2) There is a cracked floor tile observed in the kitchen. We recommend necessary repairs or replacement by a qualified licensed flooring contractor.

(3) There is damaged wood flooring observed in the family room. We recommend necessary repairs or replacing by a qualified licensed flooring contractor.

6.4 STEPS, STAIRWAYS, RAILINGS

Repair or Replace

The stair/landing railing is loose. This is a safety hazard and corrections are needed. We recommend necessary repairs for safety by a qualified licensed contractor.

6.6 DOORS (REPRESENTATIVE NUMBER)

Repair or Replace

 Several bedroom doors rub on the carpet. This can wear at the carpet in this area, and also prevents the proper air exchange when the heating/cooling systems are on. There should be a one inch clearance at the bottom of the door. We recommend necessary corrections by a qualified person.
 The door latching hardware is not installed on the master bedroom doorframe. We recommend service or replacement by a qualified person.

(3) Several door upstairs doorframes are damaged. We recommend replacement by a qualified contractor.

6.9 INTERIORS - OTHER

Information Only

(2) MAINTENANCE RECOMMENDATION: We recommend re sealing (caulking or grouting) around all sink to counter top junctions and backsplash to countertop junctions, and around all bathroom shower pan(s), curb(s), tub/ shower floor junctions, and adjacent walls throughout the house or where needed by a qualified person to help prevent moisture intrusion in these areas.

7. Plumbing System

7.4 HOSE SPIGOT(S)

Repair or Replace

The rear hose spigot has a hose that could not be made to come off as it appears to be rusted on. We recommend having the hose removed by a qualified person.

7.5 GAS/ FUEL STORAGE AND DISTRIBUTION SYSTEMS

Repair or Replace

(1) The gas piping in the attic is loose/ not properly secured as required. We recommend necessary repairs by a qualified licensed plumber.

7.6 SINK(S)

Repair or Replace

(1) There are older one piece angle stop valve(s)/ supply line(s) observed at the sinks. These one piece

angle stop valve(s)/ supply line(s) have a reputation to corrode from the inside and possible fail. A white power substance or corrosion/ calcification is observed at the one piece angle stop valve(s)/ supply line(s). We recommend that these one piece angle stop valve(s)/ supply line(s) be replaced by a qualified licensed plumber as an upgrade.

(2) Some of the sink angle stop valves are observed with calcium deposits on them. Calcium deposits can corrode or deteriorate these valves and cause potential leaks. We recommend replacing all calcified angle stop valves by a qualified licensed plumber to help prevent leaks.

(3) There is an older one piece angle stop valve/ supply line observed at the toilets. These one piece angle stop valve/ supply lines have a reputation to corrode from the inside and possible fail. A white power substance or corrosion/ calcification is observed at the one piece angle stop valves/ supply lines. We recommend that this one piece angle stop valves/ supply lines be replaced as need by a qualified licensed plumber as an upgrade.

8(B) . Hall Bathroom Upstairs

8.0.B TUB/ SHOWER ENCLOSURE

Repair or Replace

(1) The tub diverter did not operate properly when tested. This is likely due from hard water deposit build up on the tub spout mechanism. We recommend necessary repairs or replacement by a licensed plumber.

(2) The shower head arm is loose in the wall. This condition could allow water to enter behind the tub/ shower wall and could put unwanted stress on the water supply pipes. We recommend necessary repairs by a qualified licensed plumber.

8.1.B GFCI OPERATION

Repair or Replace

There is more than one GFCI receptacle installed on the bathroom circuit. This condition is not a hazard but can cause confusion to reset if one trips. Only one GFCI is required to protect all of the receptacles past the GFCI. We recommend necessary corrections by a qualified licensed electrician.

8.2.B EXHAUST FAN

Repair or Replace

The bathroom vent fan is dirty/ clogged with debris. We recommend having the bathroom vent fan cleaned by a qualified person.

8(C) . Master Bathroom

8.0.C SINK(S)

Repair or Replace

(2) Several sink faucet leak at the handles when operated. We recommend necessary repairs or replacement by a qualified licensed plumber.

8.1.C FLOOR

Repair or Replace

Carpets installed in bathrooms can trap moisture and urine, substances that can cause structural damage and health problems. Since this condition is conducive to mold growth, we advise removal of carpet from the master bathroom.

9. Laundry

9.0 WASHING MACHINE/ DRYER CONNECTION(S)

Inspected

(1) There is a three prong 220 volt receptacle installed for the dryer. Most new electric dryers require a

four prong receptacle. If you install an electric dryer, you may need to upgrade the receptacle or the dryer power cord. We recommend necessary corrections by a qualified licensed electrician. (3) SAFETY TIP : We recommend capping the unused dryer gas supply pipe until a dryer is installed for safety.

9.1 CLOTHES DRYER VENT

Repair or Replace

(1) We recommend having the dryer vent cleaned by a qualified person.

(2) The dryer vent is to long. The dryer vent maximum length of a clothes dryer duct should not exceed 25'. Any 90-degree turns in the vent reduce this 25-foot number by 5 feet. The current duct appears to be to long or have too many bends. Improper installation can be a fire hazard. We recommend necessary corrections by qualified person.

10. Fireplaces/ Chimneys

10.0 CHIMNEY(S)

Inspected

We recommend having the fireplace and chimney cleaned and inspected by a licensed chimney sweep for safety prior to using.

10.2 HEARTH/ MANTLE

Inspected

The hearth at the front of the fireplace is missing/ of inadequate size/ or an improper material. This condition does not comply with current building and fire and safety requirements. We recommend installation of a properly sized hearth by a qualified licensed contractor.

10.3 OPERATING CONTROLS

Repair or Replace

The vented gas log fireplace did not light when tested from the wall switch. The flame is controlled by the wall switch. The gas pilot may have been not on at the time of the inspection. We do not restore fuel or power to appliances that are shut off; therefore, our review is limited. Most utility companies, upon request, light pilots. We recommend further evaluation by a qualified licensed contractor and necessary repairs as needed.

11. Detectors, Safety, Security

11.0 SMOKE DETECTORS

Inspected

We recommend installing additional smoke detectors where needed to comply with current fire and safety standards and regulations as a safety upgrade.

11.1 CARBON MONOXIDE DETECTOR(S)

Inspected

(2) The quantity of Carbon Monoxide detectors that are required to be installed varies with each house. Larger houses, or those with multiple levels are required to have more CO detectors. A Carbon Monoxide detector is required on each level of a multi-level house and adjacent to each cluster of bedrooms. We recommend installing additional Carbon Monoxide detectors where needed.

11.3 FIRE SPRINKLERS

Not Inspected

There is a fire sprinkler system installed in the house and was not inspected by this company at the time of the home inspection. Inspecting fire sprinkler systems is beyond the scope of our general home inspection. We recommend having the fire sprinkler system inspected by a qualified licensed contractor prior to the end of your contingency period.

13. Cooling Equipment

13.0 COOLING EQUIPMENT

Inspected

(3) The AC unit electrical conduit is not secured to the wall as required. We recommend having the AC unit conduit secured to the wall by a qualified person.

14. Ventilation and Insulation

14.0 INSULATION IN THE ATTIC SPACE

Repair or Replace

(2) Some of the batt insulation has been moved in the attic space. This insulation was not put back into position where needed. We recommend having the insulation distributed properly/ put back into place to improve the thermal efficiency of the house by a qualified person.

(3) Insulation was noted to be in contact with several recessed lights in the attic area. This is a safety/ fire hazard. We recommend removal/ necessary corrections by a qualified person.

(4) The attic space access hatch cover is not insulated. We recommend insulating the attic access hatch cover to reduce unwanted heat loss/gain by a qualified person.

16. Built-In Kitchen Appliances

16.0 MICROWAVE (BUILT-IN)

Repair or Replace

(2) The built in microwave was installed too close to the cooktop burners. This condition could cause damage to the plastic covering and the electronic control panel due to excessive heat. We recommend replacing the microwave with a low-profile microwave or relocating it which would allow at least 18 inches of clearance between the bottom of the microwave and the cooktop burners. Lower clearances may be allowed per manufacturers listing.

16.1 DISHWASHER

Repair or Replace

(2) An air gap device was not installed for the dishwasher. An air gap device is required to prevent dirty water from being sucked back into the water supply. We recommend installation of an air gap device by a qualified license appliance contractor or plumber.

(3) The dishwasher kick plate is missing. We recommend replacing by a qualified person.

16.4 RANGE/ OVEN

Repair or Replace

(2) An anti tip bracket was not installed at the range. This bracket prevents the range from tipping forward which could cause the range to fall over. We recommend installation of an anti tip bracket by a qualified person for safety and to help prevent injury.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge <u>http://www.HomeGauge.com</u> : Licensed To Jeff Duncan